

18 Stepping motor phase current characteristics

----- rectangular characteristics – phase current
 (fullstep / with boost)
 both phases with nominal current (bipolar)

..... sinus-/cosinus characteristics – phase current
 (without boost)
 with peak value = nominal current (bipolar)

e.g. SM 88.2.18M8
 with nominal current 8 A/phase bipolar

